

# TOYOTA AGYA 1.0 A/T.

Client Copy

## Bosch Service Inspection Certificate

Inspection No:

**BOSCH**  
Service

**BATTERY DETAILS**

Age: 14 years  
Make: 1157 N/A No: 6/6C

Registration No: KZ 33 HWP

Job Card No: JC 9236

| SERVICE  |                           |           | BREAKING SYSTEM |                         |                              | STEERING SYSTEM |                   |                         |                         |     |
|--|---------------------------|-----------|-----------------|-------------------------|------------------------------|-----------------|-------------------|-------------------------|-------------------------|-----|
| OK   | Not Ok                    | Rectified | OK              | Not Ok                  | Rectified                    | OK              | Not Ok            | Rectified               |                         |     |
| <p style="font-size: 2em; transform: rotate(-45deg); opacity: 0.5;">MILITARY<br/>10000KMH<br/>01/03/2025</p> |                           |           | 50              | Brake Fluid             | C                            | ✓               | 100               | Ball Joints             | ✓                       |     |
|  |                           |           | 51              | Disc Pads Front         | mm                           | ✓               | 101               | Tie Rod Ends            | ✓                       |     |
|  |                           |           | 52              | Pad Sensors Front       | mm                           | N/A             | 102               | Control Arm             | ✓                       |     |
|  |                           |           | 53              | Discs Front             | mm                           | ✓               | 103               | Drag Link               | ✓                       |     |
|  |                           |           | 54              | Brake Caliper           | mm                           | ✓               | 104               | Stabiliser Arm          | ✓                       |     |
|  |                           |           | 55              | Brake Caliper Leak(s)   | mm                           | ✓               | <b>DRIVE LINE</b> |                         |                         |     |
|  |                           |           | 56              | Disc Pads Rear          | mm                           | N/A             | 105               | Side Shaft Oil Leak(s)  | ✓                       |     |
|  |                           |           | 57              | Pad Sensors Rear        | mm                           | N/A             | 106               | Front Wheel Bearings    | ✓                       |     |
|  |                           |           | 58              | Drums Rear              | mm                           | N/A             | 107               | Front Bearing Hubs      | ✓                       |     |
|  |                           |           | 59              | Disc Rear               | mm                           | N/A             | 108               | Rear Wheel Bearings     | ✓                       |     |
|  |                           |           | 60              | Rear Linings            | mm                           | ✓               | 109               | Rear Wheel Bearing Hubs | ✓                       |     |
|  |                           |           | 61              | Rear Cylinders          | mm                           | ✓               | 110               | CV Shafts               | ✓                       |     |
| <b>ADDITIVES MISC</b>  |                           |           | 62              | Rear Cylinder Leak(s)   | mm                           | ✓               | 111               | CV Boots                | ✓                       |     |
| 13   | Brake Cleaner             | OK        | ✓               | 63                      | Handbrake Lining             | mm              | ✓                 | 112                     | Shocks                  | ✓   |
| 14   | Radiator Flush            | OK        | ✓               | 64                      | Handbrake Cable              | mm              | ✓                 | 113                     | Springs                 | ✓   |
| 15   | Carb Cleaner              | OK        | ✓               | 65                      | Brake Master Cylinder        | mm              | ✓                 | 114                     | Shock Mountings         | ✓   |
| 16   | Engine Flush              | OK        | ✓               | 66                      | Master Cylinder Leak(s)      | mm              | ✓                 | 115                     | Wheel Nuts/Studs        | ✓   |
| <b>TRANSMISSION</b>  |                           |           | 67              | ABS System              | mm                           | ✓               | 116               | Tyres & Spare Pressure  | ✓                       |     |
| 17   | Transmission              | OK        | ✓               | 68                      | Brake Hoses                  | mm              | ✓                 | 117                     | Tyres & Spare Condition | ✓   |
| 18   | Transmission Oil          | OK        | ✓               | <b>CLUTCH SYSTEM</b>    |                              |                 | 118               | Grease Points           | ✓                       |     |
| 19   | Transmission Oil Leak(s)  | OK        | ✓               | 69                      | Clutch Fluid                 | C               | ✓                 | 119                     | Prop Shaft(s)           | N/A |
| 20   | Transfer Box              | OK        | ✓               | 70                      | Clutch Operation             | mm              | ✓                 | <b>EXHAUST SYSTEM</b>   |                         |     |
| 21   | Transfer Box Oil          | OK        | ✓               | 71                      | Clutch Master                | mm              | ✓                 | 120                     | Exhaust Silencer        | ✓   |
| 22   | Transfer Box Air Leak(s)  | OK        | ✓               | 72                      | Clutch Master Leak           | mm              | ✓                 | 121                     | Catalytic Converter     | ✓   |
| 23   | Differential              | OK        | ✓               | 73                      | Clutch Slave                 | mm              | ✓                 | 122                     | Flange Gasket           | ✓   |
| 24   | Differential Oil          | OK        | ✓               | 74                      | Clutch Slave Leak            | mm              | ✓                 | 123                     | Exhaust Manifold Gasket | ✓   |
| 25   | Differential Oil Leak(s)  | OK        | ✓               | 75                      | Clutch Cable                 | mm              | ✓                 | 124                     | Turbo Gasket(s)         | ✓   |
| 26   | Differential Lock         | OK        | ✓               | <b>COOLING SYSTEM</b>   |                              |                 | 125               | Hangers                 | ✓                       |     |
| 27   | Differential Mounting(s)  | OK        | ✓               | 76                      | Water Leaks                  | mm              | ✓                 | <b>ELECTRICAL</b>       |                         |     |
| 28   | Transmission Mounting     | OK        | ✓               | 77                      | Reservoir Bottle             | mm              | ✓                 | 125                     | ECU                     | ✓   |
| <b>ENGIN</b>   |                           |           | 78              | Anti-freeze             | C                            | ✓               | 127               | Headlights - Dim        | ✓                       |     |
| 29   | Engine Oil Leak(s)        | OK        | ✓               | 79                      | Cooling Fan                  | mm              | ✓                 | 128                     | Headlights - Bright     | ✓   |
| 30   | Oil Filler Cap            | OK        | ✓               | 80                      | Radiator Hoses               | mm              | ✓                 | 129                     | Fog Lights              | ✓   |
| 31   | Cam Belt                  | OK        | ✓               | 81                      | Water Pump                   | mm              | ✓                 | 130                     | Brake Lights            | ✓   |
| 32   | Cam Belt Tensioner        | OK        | ✓               | 82                      | Thermostat                   | mm              | ✓                 | 131                     | Park Lights             | ✓   |
| 33   | Drive Belt(s), V-Belt(s)  | OK        | ✓               | 83                      | Radiator                     | mm              | ✓                 | 132                     | Dash Lights             | ✓   |
| 34   | Tensioner/Pulleys         | OK        | ✓               | 84                      | Cooling System Pressure Test | mm              | ✓                 | 133                     | Interior Lights         | ✓   |
| 35   | Hydraulic Lifters         | OK        | ✓               | 85                      | Hose Clamps                  | mm              | ✓                 | 134                     | Flicker Lights Left     | ✓   |
| 36   | Tappet Noise              | OK        | ✓               | 86                      | Radiator Cap                 | mm              | ✓                 | 135                     | Flicker Lights Right    | ✓   |
| 37   | Throttle Assembly         | OK        | ✓               | 87                      | Cap Pressure Test            | mm              | ✓                 | 136                     | Spot Lights             | N/A |
| 38   | Turbo                     | OK        | ✓               | <b>IGNITION SYSTEM</b>  |                              |                 | 137               | Reverse Light(s)        | ✓                       |     |
| 39   | Carburetor                | OK        | ✓               | 88                      | Coil(s)                      | mm              | ✓                 | 138                     | Starter                 | ✓   |
| 40   | Injectors                 | OK        | ✓               | 89                      | Distributor                  | mm              | ✓                 | 139                     | Alternator              | ✓   |
| 41   | Fuel Pump                 | OK        | ✓               | 90                      | Distributor Cap              | mm              | ✓                 | 140                     | Battery                 | ✓   |
| 42   | Fuel Line                 | OK        | ✓               | 91                      | Rotor                        | mm              | ✓                 | 141                     | Battery Terminals       | ✓   |
| 43   | Vacuum System             | OK        | ✓               | 92                      | High Tension Leads           | mm              | ✓                 | 142                     | Battery Water           | ✓   |
| 44   | Relative Compression Test | OK        | ✓               | <b>STEERING SYSTEM</b>  |                              |                 | 143               | Power Windows           | ✓                       |     |
| 45   | Engine Mounting           | OK        | ✓               | 93                      | Steering System              | mm              | ✓                 | 144                     | Side Mirrors            | ✓   |
| <b>AIR CONDITIONER</b>   |                           |           | 94              | Steering System Leak(s) | mm                           | ✓               | 145               | Instrument              | ✓                       |     |
| 46   | Climate Control           | OK        | ✓               | 95                      | Power Steering Pump          | mm              | ✓                 | 146                     | Sensors                 | ✓   |
| 47   | Climate Temp              | OK        | ✓               | 96                      | Power Steering Fluid         | mm              | ✓                 | 147                     | Seat Belts              | ✓   |
| 48   | Compressor                | OK        | ✓               | 97                      | Power Steering Pipes         | mm              | ✓                 | 148                     | Seats                   | ✓   |
| 49   | Service Air-Con System    | OK        | ✓               | 98                      | Steering Boots               | mm              | ✓                 | 149                     | Diagnostic Check        | ✓   |
|  |                           |           |                 | 99                      | Steering Rack                | mm              | ✓                 | 150                     | Hooter                  | ✓   |

**NB: INTERNAL USE ONLY - NOT FOR FINANCE PURPOSES.**

|   |   |
|---|---|
| <p><b>ROAD TEST</b></p> <p>Performance <input checked="" type="checkbox"/></p> <p>Noise <input checked="" type="checkbox"/></p> <p>Handling <input checked="" type="checkbox"/></p> <p>Transmission <input checked="" type="checkbox"/></p> <p>Clutch <input checked="" type="checkbox"/></p> | <p style="font-size: 2em;">ALL good</p> |
| <p>Brakes <input checked="" type="checkbox"/></p> <p>Vibrations <input checked="" type="checkbox"/></p> <p>Wheel Alignment <input checked="" type="checkbox"/></p> <p>Wheel Balancing <input checked="" type="checkbox"/></p>   | <p style="font-size: 2em;">ALL good</p> |

**BCS DEALERSHIP DECLARATION**

I hereby declare that the above mentioned vehicle has been inspected by the Bosch Service dealer and at the time of this application the vehicle was found to be roadworthy and of sound mechanical condition.

Technician Name: Michael Jones

Date: 07-01-2025

Service Advisor/Managers Name: \_\_\_\_\_ print name

Signature: [Signature]

Signature: \_\_\_\_\_

**NB: INTERNAL USE ONLY - NOT FOR FINANCE PURPOSES.**