Make	LAND ROVER		
Model	DISCOVERY SPOR	T 2.0i4 D PURE	
Vin	SALCA2AN2KH789	538	
Engine Specifications	2.0	Diesel	•
Vehicle Type	SUV		
Service Plan	N/A		

Year	2017
Km	89383
Transmission	Automatic
Colour	WHITE
Branch	Bosch Car Service
Warranty Plan	N/A

Interior					
Radio / Entertainment	Within Specification	<b>~</b>	Aircon Controls	Within Specification	<b>V</b>
Cluster	Within Specification	•	Electric Windows	Within Specification	<b>~</b>

Exterior					
Windscreen	Within Specification	•	Mag Wheels	Within Specification	-
Side Mirrors / Electric	Within Specification	lacksquare	Wiper Blades	Within Specification	•

BOSCH VEHICLE INSPECTION				
Engine				
Oil Service	SERVICE DUE Km		Dip Stick	Within Specification
Oil Filter	Within Specification		Oil Filler Cap	Within Specification
Fuel/Diesel Filter	Within Specification		Fan Belt	No Cracks ▼
Air Filter	Within Specification		Fan belt Tensioner	Within Specification
Cabin Filter	Within Specification		Alternator Belt	No Cracks ▼
Spark Plugs	Not Applicable  ▼		Power Steering Belt	No Cracks   ▼
Brake Fluid	Within Specification		Aircon Belt	No Cracks
Antifreeze	Within Specification		Multi V belt	No Cracks
Rear Main Seal	No Visible Leaks  ▼		Engine Mountings	Within Specification
Sump/Gasket	No Visible Leaks  ▼		PCV Valve	Within Specification

Braking System		
Front Brake Pads	80%	<b>~</b>
Front Brake Discs	Within Specification	•
Front Brake Sensor	Not Applicable	•
Rear Brake Pads	80%	<b>~</b>
Rear Brake Discs	Within Specification	<b>~</b>
Rear Brake Sensor	Not Applicable	•
Rear Drums	Not Applicable	<b>~</b>
Rear Linings	-Select-	•
Brake Master	Within Specification	•
Hand Brake	Within Specification	<b>~</b>
Brake Calipers	Within Specification	<b>~</b>
Brake Hose	Within Specification	•

Cooling System		
Radiator	No Visible Leaks	•
Radiator Hoses	Within Specification	•
Waterpump	Within Specification	•
Thermostat	Within Specification	•
Aircon Gas	Within Specification	•
Aircon Pump	Within Specification	•
Aircon Condensor	Within Specification	<b>V</b>
Interior Fan	Within Specification	•
Interior Radiator	No Visible Leaks	<b>~</b>

Fueling System		
Intake Manifold	Within Specification	•
Throttle	Within Specification	•
Turbo	Within Specification	•
Injectors	Within Specification	•
Fuel Pump	Within Specification	•
Fuel Lines	Within Specification	•

Ignition System		
Ignition Coils	Within Specification	•
Glow Plugs	Within Specification	•
Distrubutor	Not Applicable	<b>V</b>
HT Leads	Not Applicable	•



## **BOSCH INSPECTION REPORT**

Steering & Suspension		
Steering Rack	Within Specification	~
Power Steering Pump	Within Specification	<b>V</b>
Wheel Alignment	Within Specification	<b>V</b>
CV Joints	Within Specification	<b>V</b>
CV Boots	Within Specification	<b>V</b>
Shocks Front	Within Specification	<b>V</b>
Shock Mountings Front	Within Specification	<b>V</b>
Shocks Rear	Within Specification	•
Stabilizer Links	Within Specification	•
Wheel Bearings	Within Specification	<b>~</b>
Bearing Hubs	Within Specification	▼
Control Arms	Within Specification	•
Sideshafts/Seal	No Visible Leaks	<b>v</b>
Propshaft	Not Applicable	•
Wheel Nuts/Studs	Within Specification	•
Tyres & Spare	Within Specification	•
Mag Wheels/Hub Caps	Within Specification	<b>\rightarrow</b>

Transmission & Clutch		
Clutch Kit	Not Applicable	<b>—</b>
Clutch Master	Not Applicable	•
Clutch Slave	Not Applicable	•
Clutch Cable	Not Applicable	•
Gearbox	Within Specification	•
Gear & Diff oil	Within Specification	<b>—</b>
Auto Transmission	Within Specification	lacksquare
Gear Selector	Within Specification	•
Gear Linkages	Within Specification	•

Ignition System		
Diagnostics	No Fault Code	-
Cyl Leakage Test	No Visible Leaks	-
Road Test	Within Specification	-
Handling	Within Specification	-

Concluding Remarks		

Bosch Technician	
-Select-	_

General Comments		

NEW Technician		

Date of Inspection



