| Make | BMW | | |
|-----------------------|------------------------|--------|--|
| Model | X1 sDRIVE18i A/T (F48) | | |
| Vin | WBAHS120405F02366 | | |
| Engine Specifications | 181 | Petrol | |
| Vehicle Type | SUV | | |
| Service Plan | N/A | | |

| Year | 2016 |
|---------------|-------------------|
| Km | 112260 |
| Transmission | Automatic |
| Colour | WHITE |
| Branch | Bosch Car Service |
| Warranty Plan | N/A |

| Interior | | | | | |
|-----------------------|----------------------|---|------------------|----------------------|---|
| Radio / Entertainment | Within Specification | • | Aircon Controls | Within Specification | • |
| Cluster | Within Specification | • | Electric Windows | -Select- | |

| Exterior | | | | | |
|-------------------------|----------------|----------|--------------|----------------|----------|
| Windscreen | Good Condition | • | Mag Wheels | Good Condition | — |
| Side Mirrors / Electric | Good Condition | — | Wiper Blades | Good Condition | • |

| BOSCH VEHICLE INSPECTION | | | | |
|--------------------------|----------------------|---|----------|--|
| Engine | | | | |
| Oil Service | SERVICE DUE Km | Dip Stick Within Specification | - | |
| Oil Filter | -Select- | Oil Filler Cap No Visible Leaks | - | |
| Fuel/Diesel Filter | Within Specification | Fan Belt No Cracks | - | |
| Air Filter | Within Specification | Fan belt Tensioner Within Specification | - | |
| Cabin Filter | Within Specification | Alternator Belt No Cracks | - | |
| Spark Plugs | Within Specification | Power Steering Belt Not Applicable | • | |
| Brake Fluid | Good Condition | Aircon Belt No Cracks | • | |
| Antifreeze | Good Condition | Multi V belt No Cracks | • | |
| Rear Main Seal | No Visible Leaks ▼ | Engine Mountings Within Specification | • | |
| Sump/Gasket | Not Applicable | PCV Valve Within Specification | - | |

| Braking System | | |
|--------------------|----------------------|----------|
| Front Brake Pads | 80% | - |
| Front Brake Discs | Within Specification | — |
| Front Brake Sensor | Within Specification | ~ |
| Rear Brake Pads | 80% | _ |
| Rear Brake Discs | Within Specification | ~ |
| Rear Brake Sensor | Within Specification | — |
| Rear Drums | Not Applicable | ~ |
| Rear Linings | -Select- | |
| Brake Master | Within Specification | - |
| Hand Brake | Within Specification | ~ |
| Brake Calipers | Good Condition | ~ |
| Brake Hose | No Visible Leaks | V |

| Cooling System | | |
|-------------------|----------------------|---|
| Radiator | No Visible Leaks | • |
| Radiator Hoses | No Visible Leaks | • |
| Waterpump | Within Specification | • |
| Thermostat | Within Specification | - |
| Aircon Gas | Good Condition | - |
| Aircon Pump | Within Specification | • |
| Aircon Condensor | Within Specification | • |
| Interior Fan | Good Condition | • |
| Interior Radiator | No Visible Leaks | • |

| Fueling System | | |
|-----------------|----------------------|---|
| Intake Manifold | Within Specification | • |
| Throttle | Within Specification | • |
| Turbo | Within Specification | • |
| Injectors | Within Specification | • |
| Fuel Pump | Within Specification | • |
| Fuel Lines | No Visible Leaks | • |

| Ignition System | | |
|-----------------|----------------------|---|
| Ignition Coils | Within Specification | • |
| Glow Plugs | Not Applicable | • |
| Distrubutor | Not Applicable | • |
| HT Leads | Not Applicable | • |



BOSCH INSPECTION REPORT

| Steering & Suspension | | |
|-----------------------|----------------------|----------|
| Steering Rack | Within Specification | ~ |
| Power Steering Pump | Not Applicable | - |
| Wheel Alignment | Within Specification | - |
| CV Joints | Good Condition | - |
| CV Boots | No Visible Leaks | • |
| Shocks Front | Good Condition | • |
| Shock Mountings Front | Good Condition | • |
| Shocks Rear | Good Condition | • |
| Stabilizer Links | Good Condition | • |
| Wheel Bearings | Good Condition | • |
| Bearing Hubs | Within Specification | • |
| Control Arms | Good Condition | - |
| Sideshafts/Seal | No Visible Leaks | - |
| Propshaft | -Select- | |
| Wheel Nuts/Studs | Good Condition | • |
| Tyres & Spare | Good Condition | • |
| Mag Wheels/Hub Caps | Good Condition | • |

| Transmission & Clutch | | |
|-----------------------|----------------------|---|
| Clutch Kit | Not Applicable | • |
| Clutch Master | Not Applicable | • |
| Clutch Slave | Not Applicable | • |
| Clutch Cable | Not Applicable | • |
| Gearbox | Not Applicable | • |
| Gear & Diff oil | Within Specification | • |
| Auto Transmission | Within Specification | • |
| Gear Selector | Within Specification | • |
| Gear Linkages | Within Specification | • |

| Ignition System | | |
|------------------|------------------|----------|
| Diagnostics | -Select- | |
| Cyl Leakage Test | No Visible Leaks | V |
| Road Test | Good Condition | ~ |
| Handling | Good Condition | - |

| Concluding Remarks | | |
|--------------------|--|--|
| | | |

| Bosch Technician | |
|------------------|--|
| -Select- | |

| General Comments | | |
|------------------|--|--|
| | | |
| | | |
| | | |
| | | |

| NEW Technician | | |
|-----------------|--|--|
| RIAAN MEINTJIES | | |

Date of Inspection

08-Apr-2024



