



|                       |                                |                                 |
|-----------------------|--------------------------------|---------------------------------|
| Make                  | FORD                           |                                 |
| Model                 | ECOSPORT 1.0 ECOBOOST TITANIUM |                                 |
| Vin                   | MAJAXXMRKAGY68923              |                                 |
| Engine Specifications | 1.0                            | Petrol <input type="checkbox"/> |
| Vehicle Type          | SUV                            |                                 |
| Service Plan          | N/A                            |                                 |

|               |                   |                          |
|---------------|-------------------|--------------------------|
| Year          | 2017              |                          |
| Km            | 81168             |                          |
| Transmission  | Manual            | <input type="checkbox"/> |
| Colour        | SILVER            |                          |
| Branch        | Bosch Car Service |                          |
| Warranty Plan | N/A               |                          |

## Interior

|                       |                |                          |                  |                |                          |
|-----------------------|----------------|--------------------------|------------------|----------------|--------------------------|
| Radio / Entertainment | Good Condition | <input type="checkbox"/> | Aircon Controls  | Good Condition | <input type="checkbox"/> |
| Cluster               | Good Condition | <input type="checkbox"/> | Electric Windows | Good Condition | <input type="checkbox"/> |

## Exterior

|                         |                |                          |              |                |                          |
|-------------------------|----------------|--------------------------|--------------|----------------|--------------------------|
| Windscreen              | Good Condition | <input type="checkbox"/> | Mag Wheels   | Good Condition | <input type="checkbox"/> |
| Side Mirrors / Electric | Good Condition | <input type="checkbox"/> | Wiper Blades | Renewed        | <input type="checkbox"/> |

## BOSCH VEHICLE INSPECTION

### Engine

|                    |                      |                          |                     |                      |                          |
|--------------------|----------------------|--------------------------|---------------------|----------------------|--------------------------|
| Oil Service        | SERVICE DUE Km       |                          | Dip Stick           | Within Specification | <input type="checkbox"/> |
| Oil Filter         | Within Specification | <input type="checkbox"/> | Oil Filler Cap      | No Visible Leaks     | <input type="checkbox"/> |
| Fuel/Diesel Filter | Within Specification | <input type="checkbox"/> | Fan Belt            | No Cracks            | <input type="checkbox"/> |
| Air Filter         | Within Specification | <input type="checkbox"/> | Fan belt Tensioner  | Within Specification | <input type="checkbox"/> |
| Cabin Filter       | Within Specification | <input type="checkbox"/> | Alternator Belt     | No Cracks            | <input type="checkbox"/> |
| Spark Plugs        | Within Specification | <input type="checkbox"/> | Power Steering Belt | Not Applicable       | <input type="checkbox"/> |
| Brake Fluid        | Good Condition       | <input type="checkbox"/> | Aircon Belt         | No Cracks            | <input type="checkbox"/> |
| Antifreeze         | Good Condition       | <input type="checkbox"/> | Multi V belt        | No Cracks            | <input type="checkbox"/> |
| Rear Main Seal     | No Visible Leaks     | <input type="checkbox"/> | Engine Mountings    | Good Condition       | <input type="checkbox"/> |
| Sump/Gasket        | No Visible Leaks     | <input type="checkbox"/> | PCV Valve           | Within Specification | <input type="checkbox"/> |

| Braking System     |                      |                                  |
|--------------------|----------------------|----------------------------------|
| Front Brake Pads   | 100%                 | <input type="button" value="v"/> |
| Front Brake Discs  | Within Specification | <input type="button" value="v"/> |
| Front Brake Sensor | Not Applicable       | <input type="button" value="v"/> |
| Rear Brake Pads    | -Select-             | <input type="button" value="v"/> |
| Rear Brake Discs   | Not Applicable       | <input type="button" value="v"/> |
| Rear Brake Sensor  | Not Applicable       | <input type="button" value="v"/> |
| Rear Drums         | Within Specification | <input type="button" value="v"/> |
| Rear Linings       | 80%                  | <input type="button" value="v"/> |
| Brake Master       | Within Specification | <input type="button" value="v"/> |
| Hand Brake         | Within Specification | <input type="button" value="v"/> |
| Brake Calipers     | Good Condition       | <input type="button" value="v"/> |
| Brake Hose         | No Visible Leaks     | <input type="button" value="v"/> |

| Cooling System    |                      |                                  |
|-------------------|----------------------|----------------------------------|
| Radiator          | No Visible Leaks     | <input type="button" value="v"/> |
| Radiator Hoses    | No Visible Leaks     | <input type="button" value="v"/> |
| Waterpump         | Within Specification | <input type="button" value="v"/> |
| Thermostat        | Within Specification | <input type="button" value="v"/> |
| Aircon Gas        | Good Condition       | <input type="button" value="v"/> |
| Aircon Pump       | Within Specification | <input type="button" value="v"/> |
| Aircon Condensor  | Good Condition       | <input type="button" value="v"/> |
| Interior Fan      | Good Condition       | <input type="button" value="v"/> |
| Interior Radiator | No Visible Leaks     | <input type="button" value="v"/> |

| Fueling System  |                      |                                  |
|-----------------|----------------------|----------------------------------|
| Intake Manifold | Within Specification | <input type="button" value="v"/> |
| Throttle        | Within Specification | <input type="button" value="v"/> |
| Turbo           | Within Specification | <input type="button" value="v"/> |
| Injectors       | Within Specification | <input type="button" value="v"/> |
| Fuel Pump       | Good Condition       | <input type="button" value="v"/> |
| Fuel Lines      | No Visible Leaks     | <input type="button" value="v"/> |

| Ignition System |                      |                                  |
|-----------------|----------------------|----------------------------------|
| Ignition Coils  | Within Specification | <input type="button" value="v"/> |
| Glow Plugs      | Not Applicable       | <input type="button" value="v"/> |
| Distrubutor     | Not Applicable       | <input type="button" value="v"/> |
| HT Leads        | Not Applicable       | <input type="button" value="v"/> |



| Steering & Suspension |                      |                          |
|-----------------------|----------------------|--------------------------|
| Steering Rack         | Within Specification | <input type="checkbox"/> |
| Power Steering Pump   | Not Applicable       | <input type="checkbox"/> |
| Wheel Alignment       | Within Specification | <input type="checkbox"/> |
| CV Joints             | Within Specification | <input type="checkbox"/> |
| CV Boots              | No Visible Leaks     | <input type="checkbox"/> |
| Shocks Front          | Good Condition       | <input type="checkbox"/> |
| Shock Mountings Front | Good Condition       | <input type="checkbox"/> |
| Shocks Rear           | Renewed              | <input type="checkbox"/> |
| Stabilizer Links      | Good Condition       | <input type="checkbox"/> |
| Wheel Bearings        | Good Condition       | <input type="checkbox"/> |
| Bearing Hubs          | Good Condition       | <input type="checkbox"/> |
| Control Arms          | Good Condition       | <input type="checkbox"/> |
| Sideshafts/Seal       | No Visible Leaks     | <input type="checkbox"/> |
| Propshaft             | Not Applicable       | <input type="checkbox"/> |
| Wheel Nuts/Studs      | Good Condition       | <input type="checkbox"/> |
| Tyres & Spare         | Good Condition       | <input type="checkbox"/> |
| Mag Wheels/Hub Caps   | Good Condition       | <input type="checkbox"/> |

| Transmission & Clutch |                      |                          |
|-----------------------|----------------------|--------------------------|
| Clutch Kit            | Within Specification | <input type="checkbox"/> |
| Clutch Master         | Within Specification | <input type="checkbox"/> |
| Clutch Slave          | Within Specification | <input type="checkbox"/> |
| Clutch Cable          | Not Applicable       | <input type="checkbox"/> |
| Gearbox               | Within Specification | <input type="checkbox"/> |
| Gear & Diff oil       | Within Specification | <input type="checkbox"/> |
| Auto Transmission     | Not Applicable       | <input type="checkbox"/> |
| Gear Selector         | Within Specification | <input type="checkbox"/> |
| Gear Linkages         | Within Specification | <input type="checkbox"/> |

| Ignition System  |                  |                          |
|------------------|------------------|--------------------------|
| Diagnostics      | No Visible Leaks | <input type="checkbox"/> |
| Cyl Leakage Test | No Visible Leaks | <input type="checkbox"/> |
| Road Test        | Good Condition   | <input type="checkbox"/> |
| Handling         | Good Condition   | <input type="checkbox"/> |

**Concluding Remarks**

---

**Bosch Technician**

-Select-

**General Comments**

---

**NEW Technician**

RIAAAN MEINTJIES

**Date of Inspection**

29-Mar-2024

