

# All System Diagnostic Report

The Report is created by **THINKCAR**

## Repair Shop

Shop Name:bosch service centre

Address:564 Steve Biko Road

Telephone:0123355737

Email:lukas@boschgezina.co.za

Sn:988579800333

Time:2024-10-12 09:14:46

Technician Name:john

Order no:

Service fee:

Notes:

## Vehicle Information

Year:2019

Make:USAFORD

Model:Figo/Ka

VIN:MAJGXXMTKGKC55757

Odometer:59046 km

Vehicle Software Version:V10.86

## Inspection Result

The following systems are OK:

- 1.ABS (Anti-Lock Brake System)
- 2.ACM (Audio Front Control Module)
- 3.BCM (Body Control Module)
- 4.HVAC (Heating, Ventilation And Air Conditioning)
- 5.IPC (Instrument Panel Cluster)
- 6.PCM (Powertrain Control Module)
- 7.PSCM (Power Steering Control Module)
- 8.RCM (Restraints Control Module)