

# All System Diagnostic Report

The Report is created by **THINKCAR**

---

## Repair Shop

Shop Name:  
Address:  
Telephone:N/A  
Sn:988579800333  
Time:02/12/2025 12:52:11  
Technician Name:shaun

---

## Vehicle Information

Make:BXGM  
Model:chev ute  
VIN:admjf4hr4f4727247  
Displacement:D 1.6 TCI-U2  
Odometer:109265 km  
Vehicle Software Version:V10.02

---

## Inspection Result

The following systems are OK:

- 1.10-> Acdelco GMPTHS0C
- 2.09-> MULTEC H N14YFH-C
- 3.08-> IMMOBILIZER GM-3
- 4.09-> IMMOBILIZER 2
- 5.08-> PAINEL GM-9
- 6.10-> ABS EBCM
- 7.09-> ABS BOSCH 8.1
- 8.GM-9 PANEL