

# All System Diagnostic Report

The Report is created by **THINKCAR**

## Repair Shop

Shop Name:Citton cars  
Address:564 Steve Biko Road  
Telephone:0123355737  
Email:johan@boschgezina.co.za  
Sn:988579800333  
Time:2023-12-11 18:40:34  
Technician Name:Adriaan  
Customer Name:Citton cars

## Vehicle Information

Year:2014.04  
Make:BMW  
Model:i3  
VIN:WBY1Z22080V221317  
Displacement:G 1.6 MPI  
Odometer:56991 km  
Vehicle Software Version:V10.26

## Inspection Result

The following systems are OK:

- 1.SRS (Supplemental Inflatable Restraint System - AIRBAG/SGM-SIM)
- 2.SME (Battery Management Electronics)
- 3.ZGM (Central Gateway Module)
- 4.ECM (Engine Control Module - DME/DDE)
- 5.LIM (Charging Interface Module)
- 6.KLE (Convenience Charging Electronics)
- 7.EME (Electrical Machine Electronics)/RLM\_1R (Tail Light Module, Outer Right)
- 8.ABS (Anti-Lock Braking System - DSC)
- 9.PMA (Parking Assistant)
- 10.EPS (Electronic Power Steering)
- 11.CAS (Car Access System - CAS/FEM/BDC)
- 12.FZD (Function Center, Roof)
- 13.GWS (Gear Selector Switch)
- 14.IC (Instrument Cluster - INSTR)
- 15.ECALL (Emergency Call)
- 16.CIC (Car Information Computer)
- 17.ZBE/CON (Controller)
- 18.AC (Air Conditioning - IHKA)