

# All System Diagnostic Report

The Report is created by **THINKCAR**

## Repair Shop

Shop Name:Citton Cars  
Address:564 Steve Biko Road  
Telephone:0123355737  
Email:juan-dre@boschgezina.co.za  
Sn:988579800333  
Time:2024-02-28 07:41:55  
Technician Name:Wimpie F  
Customer Name:cittoncars

## Vehicle Information

Make:Renault  
Model:kwid  
VIN:meebba005k8687389  
Odometer:101048 km  
Vehicle Software Version:V10.62

## Inspection Result

The following systems are OK:

- 1.ABS (Anti-Lock Braking System)
- 2.ACM (Audio Control Module)
- 3.APIM (Accessory Protocol Interface Module)
- 4.BCMII (Body Control Module)
- 5.C-CM (Cruise-Control Module)
- 6.DDM (Driver Front Door Module)
- 7.FCIM (Front Controls Interface Module)
- 8.FDSM (Front Distance Sensing Module)
- 9.HVAC (Heating Ventilation Air Conditioning)
- 10.IPC (Instrument Panel Control Module)
- 11.IPM-A (Image Processing Module A)
- 12.PAM (Parking Aid Module)
- 13.PCM (Powertrain Control Module)
- 14.PDM (Passenger Front Door Module)
- 15.PSCM (Power Steering Control Module)
- 16.RCM (Restraint Control Module)
- 17.RFA (Remote Function Actuator)
- 18.SASM (Steering Angle Sensor Module)
- 19.SOD-L (Side Obstacle Detection Control Module - Left)
- 20.SOD-R (Side Obstacle Detection Control Module - Right)