

All System Diagnostic Report

The Report is created by **THINKCAR**

Repair Shop

Shop Name: citton cars
Address: 564 Steve Biko Road
Telephone: 0123355737
Email: karika@boschgezina.co.za
Sn: 988579800333
Time: 2024-04-08 13:26:06
Technician Name: Riaan
Order no:
Service fee:
Notes:

Vehicle Information

Year: 2016.07
Make: BMW
Model: X1 sDrive18i
VIN: WBAHS120405F02366
Odometer: 112265 km
Vehicle Software Version: V10.26

Inspection Result

CAS (Car Access System - CAS/FEM/BDC) 2 problems exist

1.0301A0 Power Window Regulator, Rear Passenger Door: System Not Normalised.	Permanent
2.8040BD Terminal 30F Reset Or Deactivated	Intermittent

The following systems are OK:

- 1.SRS (Supplemental Inflatable Restraint System - AIRBAG/SGM-SIM)
- 2.ZGM (Central Gateway Module)
- 3.ECM (Engine Control Module - DME/DDE)
- 4.TCM (Transmission Control Module - EGS)
- 5.ABS (Anti-Lock Braking System - DSC)
- 6.PMA (Parking Assistant)
- 7.EPS (Electronic Power Steering)
- 8.FZD (Function Center, Roof)
- 9.IC (Instrument Cluster - INSTR)
- 10.ECALL (Emergency Call)
- 11.CIC (Car Information Computer)
- 12.ZBE/CON (Controller)
- 13.AC (Air Conditioning - IHKA)