

SOUTH AFRICA
**NOTICE IN RESPECT OF
 PARTICULARS OF VEHICLE**
 (National Road Traffic Act, 1996)

REPUBLIEK VAN SUID-AFRIKA

**KENNISGEWING IN VERBAND MET
 BESONDERHEDE VAN VOERTUIG**
 (Nasionale Padverkeerswet, 1996)

| | | | | | | | |
|---|---|--|---------------------------------|---|---|---|-----------------------|
| Licence number and vehicle register number | HJ04HDGP | and/en | YBM931W | Lisensienommer en voertuigregisternommer | | | |
| Date of issue | 2024-07-29 | | | Datum van uitreiking | | | |
| Infrastructure number of testing station | 49511356 | | | Infrastruktuurnommer van toetsstasie | | | |
| Infrastructure number and signature of examiner of vehicles | 4951302D | | | Infrastruktuurnommer en handtekening van ondersoeker van voertuie | | | |
| Chassis number or VIN/ Engine number | WF0DXXGAKDHP41587 | / | HP41587 | Onderstelnummer of VIN/ Enjinnommer | | | |
| Make | FORD | | | Fabrikaat | | | |
| Series name | FIESTA | | | Reeksnaam | | | |
| Manufacturer's model derivative | 1.0LFOXGTDITANIUM5 | | | Vervaardiger se modelafgeleide | | | |
| Vehicle category | Light passenger mv (less than 12 persons) | | | Voertuigkategorie | | | |
| Driven | Self-propelled / Selfgedrewe | | | Aandrywing | | | |
| Vehicle description on NaTIS | Hatch back / Luikrug | | | Voertuigbeskrywing op NaVIS | | | |
| Vehicle description as seen by Examiner | Hatch back / Luikrug | | | Voertuigbeskrywing soos deur Ondersoeker gesien | | | |
| Net power and engine capacity | 92 | kW and/en | 998 | cm ³ | Netto drywing en enjinkapasiteit | | |
| Fuel type | Petrol / Petrol | | | Tipe brandstof | | | |
| Tare (T) and gross vehicle mass (GVM) | 1118 | kg and/en | 1575 | kg | Tarra (T) en bruto voertuigmassa (BVM) | | |
| Transmission | Manual / Hand | | | Transmissie | | | |
| Main colour/ Colour change | White / Wit | | | / N | Hoofkleur/ Kleur verander | | |
| Passenger capacity: seated (incl driver) | 5 | Passasierskapasiteit: sittend (insl bestuurder) | Passenger capacity: standing | 0 | Passasierskapasiteit: staande | | |
| Gross combination mass (GCM): kg* | 2325 | | | Bruto kombinasie- massa (BKM): kg* | | | |
| Total number of axles and driving axles | 2 | and | 1 | Total aantal asse en aandrywende asse | Total number of wheels | 4 | Total aantal wiele |
| Overall length: mm* | 4412 | Algehele lengte: mm* | Overall width: mm* | 1722 | Algehele breedte: mm* | | |
| Overall height: mm* | 1495 | Algehele hoogte: mm* | Rear overhang: mm* | 675 | Agteroorstek: mm* | | |
| Wheelbase: mm* | 2489 | Asafstand: mm* | Track: mm* | 1474 | Spoor: mm* | | |
| Gearbox number/ Differential number* | / | | | Ratkasnummer/ Ewenaarnommer* | | | |
| Police clearance required | None / Geen | | | Polisieklaring verlang | | | |
| Roadworthy test status | Pass and issued / Slaag en uitgereik | | | Padwaardigheidstoets status | | | |
| Roadworthy status | Roadworthy / Padwaardig | | | Padwaardigheid status | | | |

NOTE: The certification of the roadworthiness of a motor vehicle cannot in any way be regarded as a guarantee as to the soundness of the construction or mechanical condition of the vehicle concerned.

*Optional

LET WEL: Die sertifisering van die padwaardigheid van 'n motorvoertuig kan geensins beskou word as 'n waarborg dat die konstruksie of meganiese toestand van die betrokke voertuig sonder enige gebrek is nie.

*Opsioneel