

ROADWORTHINESS TEST SHEET

Test Number

43511

Licence number and **GV42DH GP** or ☐ not yet allocated and **C53919X** vehicle register number
 Chassis number/VIN **NFAFXKMJ2PLT56082** white
 Make and series name **FORD RANGER** **PICK-UP**

NOTE: The figures between brackets refer to the clauses in SANS 10047

01 IDENTIFICATION AND DOCUMENTATION		Fuel system and fuel tank (5.43)	☒	Suspension units (5.44)	☒
Identification - SAPS Clearance (4.4)		Retro-reflectors (5.59)	☒		
Information and registration details (5.2)		Retro-reflective material (5.60)	☒		
		Stairs and passage (6.7, 6.8)	☒		
		Safety design (5.62)	☒	Shock absorbers (5.45)	☒
		Twist locks for securing containers (5.63)	☒	Stub axles, wheel bearings, control arms and kingpins (5.46)	☒
		Emergency warning triangle/Emergency exit (6.3)	☒	Stabilizers and anti-roll bars (5.47)	☒
02 ELECTRICAL SYSTEM		04 BRAKING SYSTEM		Wheel alignment (5.51) $\theta = -22$	☒
Windscreen wipers (5.24)		Brake formula: $2093 \times 4.4 / 1000 = 9.2m$		Wheel alignment reading $R = 0.00$	☒
Hooter (5.26)		Park brake: 12% of brake force = $4.6N$			
Electrical wiring and equipment (5.38)					
Lamps and lighting (5.58)		Air or vacuum warning device (5.31)	☒	07 STEERING	
		Build-up of air pressure or vacuum (5.32)	☒	Steering wheel (5.28)	☒
		Hand levers for mechanical systems (5.33)	☒	Steering column (5.29)	☒
		Service brake pedal (5.34)	☒	Handlebars and steering (5.30)	☒
		Service brake operation (5.35)	☒	Steering mechanism (5.48)	☒
Flasher type direction indicators (5.61)		Hand-operated air brake valves (5.36)	☒	Power Steering (5.49)	☒
		Braking system - general (5.52)	☒		
		Braking system - specific items (5.53)	☒	08 ENGINE <i>covered</i>	
03 FITTINGS AND EQUIPMENT		Trailer parking brake (5.54)	☒	Smoke emission (5.3)	☒
Bumper bars (5.7)		Brakes and braking performance (5.55, 5.56)	☒	Engine (5.39) <i>Diesel</i>	☒
Wheel flaps (5.8)		Service brake		7M2LPHT56082	
Trailer coupling on drawing vehicle (5.9)		L/F	R/F	Engine and transmission mountings (5.40)	☒
Coupling on trailer (5.10)		L/R1 3.7	R/R1 3.5	Oil leaks (5.42)	☒
Tilt angle (6.6)		L/R2 3.1	R/R2 2.9		
Coupling socket (5.10)		L/R3	R/R3	09 EXHAUST SYSTEM	
Sides and roof (6.2, 8.2)		Parking/Emergency brake	☒	Exhaust system (5.3)	☒
Rear underrun (5.12)		L/S1 2.6	R/S1 2.5		
Mudguards (5.13)		L/S2	R/S2	10 TRANSMISSION AND DRIVE	
Cab mounting (5.14)		L/S3	R/S3	Drive train (5.41, 5.50) <i>Automatic</i>	☒
Load body or side car (5.15)		05 WHEELS <i>GRABBER</i>		11 INSTRUMENTS	
Motor cycle fittings (5.16)		Road wheels and hubs (5.4)	☒	Speedometer (5.25)	☒
Safety belts (5.17)		Size and type of tyres (5.5)	☒	12 DIMENSIONS	
Doors (5.18)		Condition of tyres (5.6)	☒	Dimensions (5.57)	☒
Floor and steps (5.19)		$265/70 R17$			
Seats (5.20)		06 SUSPENSION AND UNDERCARRIAGE			
Mirrors (5.21)		Cleanliness (4.3)	☒		
View to front and sides (5.22)		Chassis or frame (5.37)	☒		
Windows and windscreen (5.23)					
Driving controls (5.27)					
Number of passengers (6.9, 6.11, 8.6) <i>PS</i>					
School bus (6.10, 6.11)					

Pit no. and position in lane	A and C3	Pit no. and position in lane	
Test date	2:0 2503	Re-test date	2:0 :
Time	from 1030 to 1056	Time	from : to :
Odometer reading	1071067	Odometer reading	
Result	Pass	Result	Pass
Testing station infrastructure no.	06000717	Examiner of vehicles infrastructure no.	
Examiner of vehicles infrastructure no.	49813887	Name and signature	
Name and signature	Fullyfield	Remarks	
Remarks	tyres If = 7mm Pf = 7mm IR = 7mm PR = 7mm		

APPLICATION FOR CERTIFICATION

Fees paid and receipt number for roadworthiness test

R 700,93

and en

8P230009943511

AANSOEK OM CERTIFISERING

Gelde betaald en kwitantienummer van padwaardigheidsfoto's