

# All System Diagnostic Report

The Report is created by **THINKCAR**

---

## Repair Shop

Shop Name:  
Address:  
Telephone:N/A  
Sn:988579800333  
Time:03/03/2025 09:32:21  
Technician Name:shaun

---

## Vehicle Information

Make:TOYOTA  
Model:Hilux  
VIN:AHTKB3CD302641699  
Odometer:118459.00 km  
Vehicle Software Version:V10.52

---

## Inspection Result

The following systems are OK:

- 1.EOBD/OBD II
- 2.ECMTCM (Engine and Transmission)
- 3.RCC (Radar Cruise) 1
- 4.ABS (Brake Control)
- 5.PPS (Progressive Power Steering)
- 6.SRS (Supplemental Inflatable Restraint System)
- 7.FWD (Four Wheel Drive)
- 8.CM (Combination Meter)
- 9.NS (Navigation System)
- 10.CGW (Central Gateway)
- 11.CS (Clearance Sonar)
- 12.IMMO (Immobiliser)