

KM: 81199 Sales Person - TSQENG Bosch Copy

Bosch Service Inspection Certificate



Inspection No:

BATTERY DETAILS

± Age 11 years
 Make Mercedes No. _____

Registration No: LB33UTGP

Job Card No: JC 7790

SERVICE	OK	Not Ok	Rectified	BREAKING SYSTEM	OK	Not Ok	Rectified	STEERING SYSTEM	OK	Not Ok	Rectified										
1 Service	/			50 Brake Fluid	/			100 Ball Joints	/												
2 Spark Plugs	/			51 Disc Pads Front	/			101 Tie Rod Ends	/												
3 Points & Condenser	/			52 Pad Sensors Front	/			102 Control Arm	/												
4 Oil	/			53 Discs Front	/			103 Drag Link	/												
5 Oil Filter	/			54 Brake Caliper	/			104 Stabiliser Arm	/												
6 Fuel Filter	/			55 Brake Caliper Leak(s)	/			DRIVE LINE			OK	Not Ok	Rectified								
7 Air Filter	/			56 Disc Pads Rear	/			105 Side Shaft Oil Leak(s)	/												
8 Pollen Filter	/			57 Pad Sensors Rear	/			106 Front Wheel Bearings	/												
9 Other Filter(s)	/			58 Drums Rear	/			107 Front Bearing Hubs	/												
10 Wiper Blades	/			59 Disc Rear	/			108 Rear Wheel Bearings	/												
11 Windscreen Washers	/			60 Rear Linings mm	/			109 Rear Wheel Bearing Hubs	/												
12 Pedal Rubbers	/			61 Rear Cylinders	/			110 CV Shafts	/												
ADDITIVES MISC			OK	Not Ok	Rectified	CLUTCH SYSTEM			OK	Not Ok	Rectified	ELECTRICAL			OK	Not Ok	Rectified				
13 Brake Cleaner	/			62 Rear Cylinder Leak(s)	/			69 Clutch Fluid	/			126 ECU	/								
14 Radiator Flush	/			63 Handbrake Lining mm	/			70 Clutch Operation	/			127 Headlights - Dim	/								
15 Carb Cleaner	/			64 Handbrake Cable	/			71 Clutch Master	/			128 Headlights - Bright	/								
16 Engine Flush	/			65 Brake Master Cylinder	/			72 Clutch Master Leak	/			129 Fog Lights	/								
TRANSMISSION			OK	Not Ok	Rectified	COOLING SYSTEM			OK	Not Ok	Rectified	130 Brake Lights	/								
17 Transmission	/			66 Master Cylinder Leak(s)	/			73 Clutch Slave	/			131 Park Lights	/								
18 Transmission Oil	/			67 ABS System	/			74 Clutch Slave Leak	/			132 Dash Lights	/								
19 Transmission Oil Leak(s)	/			68 Brake Hoses	/			75 Clutch Cable	/			133 Interior Lights	/								
20 Transfer Box	/			IGNITION SYSTEM			OK	Not Ok	Rectified	STEERING SYSTEM			OK	Not Ok	Rectified	EXHAUST SYSTEM			OK	Not Ok	Rectified
21 Transfer Box Oil	/			76 Water Leaks	/			88 Coil(s)	/			120 Exhaust Silencer	/								
22 Transfer Box air Leak(s)	/			77 Reservoir Bottle	/			89 Distributor	/			121 Catalytic Converter	/								
23 Differential	/			78 Antifreeze	/			90 Distributor Cap	/			122 Flange Gasket	/								
24 Differential Oil	/			79 Cooling Fan	/			91 Rotor	/			123 Exhaust Manifold Gasket	/								
25 Differential Oil Leak(s)	/			80 Radiator Hoses	/			92 High Tension Leads	/			124 Turbo Gasket(s)	/								
26 Differential Lock	/			81 Water Pump	/			STEERING SYSTEM			OK	Not Ok	Rectified	EXHAUST SYSTEM			OK	Not Ok	Rectified		
27 Differential Mounting(s)	/			82 Thermostat	/			93 Steering System	/			125 Hangers	/								
28 Transmission Mounting	/			83 Radiator	/			94 Steering System Leak(s)	/			ELECTRICAL			OK	Not Ok	Rectified				
ENGIN			OK	Not Ok	Rectified	IGNITION SYSTEM			OK	Not Ok	Rectified	126 ECU	/								
29 Engine Oil Leak(s)	/			84 Cooling System Pressure Test	/			88 Coil(s)	/			127 Headlights - Dim	/								
30 Oil Filler Cap	/			85 Hose Clamps	/			89 Distributor	/			128 Headlights - Bright	/								
31 Cam Belt	/			86 Radiator Cap	/			90 Distributor Cap	/			129 Fog Lights	/								
32 Cam Belt Tensioner	/			87 Cap Pressure Test	/			91 Rotor	/			130 Brake Lights	/								
33 Drive Belt(s)/V-Belt(s)	/			IGNITION SYSTEM			OK	Not Ok	Rectified	STEERING SYSTEM			OK	Not Ok	Rectified	EXHAUST SYSTEM			OK	Not Ok	Rectified
34 Tensioner/Pulleys	/			88 Coil(s)	/			92 High Tension Leads	/			131 Park Lights	/								
35 Hydraulic Lifters	/			89 Distributor	/			STEERING SYSTEM			OK	Not Ok	Rectified	132 Dash Lights	/						
36 Tappet Noise	/			90 Distributor Cap	/			93 Steering System	/			133 Interior Lights	/								
37 Throttle Assembly	/			91 Rotor	/			94 Steering System Leak(s)	/			134 Flicker Lights Left	/								
38 Turbo	/			92 High Tension Leads	/			95 Power Steering Pump	/			135 Flicker Lights Right	/								
39 Carburetor	/			STEERING SYSTEM			OK	Not Ok	Rectified	EXHAUST SYSTEM			OK	Not Ok	Rectified	ELECTRICAL			OK	Not Ok	Rectified
40 Injectors	/			93 Steering System	/			96 Power Steering Fluid	/			136 Spot Lights	/								
41 Fuel Pump	/			94 Steering System Leak(s)	/			97 Power Steering Pipes	/			137 Reverse Light(s)	/								
42 Fuel Line	/			95 Power Steering Pump	/			98 Steering Boots	/			138 Starter	/								
43 Vacuum System	/			96 Power Steering Fluid	/			99 Steering Rack	/			139 Alternator	/								
44 Relative Compression Test	/			97 Power Steering Pipes	/			STEERING SYSTEM			OK	Not Ok	Rectified	140 Battery	/						
45 Engine Mounting	/			98 Steering Boots	/			93 Steering System	/			141 Battery Terminals	/								
AIR CONDITIONER			OK	Not Ok	Rectified	STEERING SYSTEM			OK	Not Ok	Rectified	142 Battery Water	/								
46 Climate Control	/			94 Steering System Leak(s)	/			94 Steering System Leak(s)	/			143 Power Windows	/								
47 Climate Temp	/			95 Power Steering Pump	/			95 Power Steering Pump	/			144 Side Mirrors	/								
48 Compressor	/			96 Power Steering Fluid	/			96 Power Steering Fluid	/			145 Instrument	/								
49 Service Air-Con System	/			97 Power Steering Pipes	/			97 Power Steering Pipes	/			146 Sensors	/								

NB: INTERNAL USE ONLY - NOT FOR FINANCE PURPOSES.

NB: INTERNAL USE ONLY - NOT FOR FINANCE PURPOSES.

ROAD TEST

Performance

Noise

Handling

Transmission

Clutch

Road test done

Brakes

Vibrations

Wheel Alignment

Wheel Balancing

all good

BCS DEALERSHIP DECLARATION

I hereby declare that the above mentioned vehicle has been inspected by the Bosch Service dealer and at the time of this application the vehicle was found to be roadworthy and in sound mechanical condition.

Technician Name: Michael Jones

Service Advisor/Managers Name: _____ print name

Date: 22-10-2024

Signature: [Signature]

Signature: _____