

All System Diagnostic Report

The Report is created by **THINKCAR**

Repair Shop

Shop Name:

Address:

Telephone:N/A

Sn:988579800333

Time:03/12/2025 11:06:38

Technician Name:DRIES

Vehicle Information

Make:BENZ

Model:176.043 - A 200 BlueEFFICIENCY Sedan

VIN:WDD1760432J499567

Odometer:113365 km

Vehicle Software Version:V10.98

Inspection Result

The following systems are OK:

- 1.ME - MOTOR ELECTRONICS FOR COMBUSTION ENGINE(ECM)
- 2.FSCU - Control Unit 'Fuel pump'(N118)
- 3.VGS/DKG/DCT - Transmission Control Unit (TCM)
- 4.EPB - Electrical Parking Brake(EPB)
- 5.ESP - Electronic Stability program(N30/4)
- 6.ES - Electrical Power Steering(N68)
- 7.TPC - Tire Pressure Monitoring System(TPMS)(N88)
- 8.EIS/EZS - Electronic Ignition lock(N73)
- 9.ABA - Active Brake Assist (A108))
- 10.SAM - Signal Acquisition And Actuation module(N10)
- 11.AB - Supplemental Restraint system(N2/10)
- 12.RevGUS_VL - Left Front Reversible Emergency Tensioning retractor(A76)
- 13.RevGUS_VR - Right Front Reversible Emergency Tensioning retractor(A76/1)
- 14.ATA - ATA[EDW]/tow-away Protection/Interior protection(N26/6)
- 15.SG-SW_L - Left Headlamp
- 16.SG-SW_R - Right Headlamp
- 17.SD - Sliding Roof/Panoramic Sliding Sunroof
- 18.MFK - Multifunction camera(A40/11)
- 19.IC - Instrument cluster(A1)
- 20.SCCM - Steering Column module(N80)
- 21.PTS - PARKTRONIC(N62)
- 22.ZBE - Operating Unit Of Control Unit'Audio Or COMAND'(A40/9)
- 23.ZAN - Audio/COMAND display(A40/8)
- 24.Audio 20/COMAND-Audio Or COMAND(A2-A40/3)
- 25.DCU_FL - Left Front door(N69/1)
- 26.DCU_FR - Right Front door(N69/2)
- 27.AC - Air Conditioning(N22/7)