

All System Diagnostic Report

The Report is created by **THINKCAR**

Repair Shop

Shop Name: bosch service centre
Address: 564 Steve Biko Road
Telephone: 0123355737
Email: mariska@boschgezina.co.za
Sn: 988579800333
Time: 2024-10-02 11:26:44
Technician Name: Ricardo
Order no:
Service fee:
Notes:

Vehicle Information

Year: 2018
Make: USAFORD
Model: Fiesta 2017
VIN: WF0JXXGAHJJU26367
Displacement: G 1.1 MPI
Odometer: 95545 km
Vehicle Software Version: V10.86

Inspection Result

The following systems are OK:

1. ABS (Anti-Lock Brake System)
2. ACM (Audio Front Control Module)
3. APIM (Accessory Protocol Interface Module)
4. BCM (Body Control Module)
5. DDM (Driver Door Module)
6. GWM (Gateway Module A)
7. HVAC (Heating, Ventilation And Air Conditioning)
8. IPC (Instrument Panel Cluster)
9. PAM (Parking Assist Control Module)
10. PCM (Powertrain Control Module)
11. PDM (Passenger Door Module)
12. PSCM (Power Steering Control Module)
13. RCM (Restraints Control Module)
14. SCCM (Steering Column Control Module)