

Engine

# **BOSCH INSPECTION REPORT**

JOB CARD NUMBER 14536

Make	BMW
Model	320i M SPORT A/T (F30)
Vin	ADNUSN1D5U0163656
Engine Specifications	Petrol
Vehicle Type	S/C
Service Plan	N/A

Year	2016
Km	127428
Transmission	Automatic
Colour	RED
Branch	Bosch Car Service
Warranty Plan	N/A

Interior					
Radio / Entertainment	Good Condition	•	Aircon Controls	Good Condition	-
Cluster	Good Condition	-	Electric Windows	Good Condition	•

Exterior					
Windscreen	Within Specification	-	Mag Wheels	Within Specification	-
Side Mirrors / Electric	Good Condition	-	Wiper Blades	Within Specification	•

## **BOSCH VEHICLE INSPECTION**

8					
Oil Service		Km	Dip Stick	Good Condition	•
Oil Filter	Not Applicable	•	Oil Filler Cap	Good Condition	•
Fuel/Diesel Filter	Renewed	•	Fan Belt	Within Specification	•
Air Filter	Within Specification	•	Fan belt Tensioner	Not Applicable	•
Cabin Filter	Within Specification	-	Alternator Belt	Not Applicable	•
Spark Plugs	Within Specification	•	Power Steering Belt	Not Applicable	•
Brake Fluid	Within Specification	-	Aircon Belt	Not Applicable	•
Antifreeze	Within Specification	•	Multi V belt	Within Specification	<b>•</b>
Rear Main Seal	Within Specification	•	Engine Mountings	Within Specification	•
Sump/Gasket	Within Specification	•	PCV Valve	Good Condition	•



Braking	System

Front Brake Pads	-Select-	•
Front Brake Discs	Good Condition	•
Front Brake Sensor	Good Condition	-
Rear Brake Pads	-Select-	-
Rear Brake Discs	Good Condition	-
Rear Brake Sensor	Good Condition	•
Rear Drums	Not Applicable	•
Rear Linings	-Select-	•
Brake Master	Within Specification	•
Hand Brake	Good Condition	•
Brake Calipers	Good Condition	•
Brake Hose	Good Condition	•

Cooling System		
Radiator	Good Condition	•
Radiator Hoses	Good Condition	•
Waterpump	Good Condition	•
Thermostat	Good Condition	•
Aircon Gas	Good Condition	•
Aircon Pump	Good Condition	•
Aircon Condensor	Good Condition	•
Interior Fan	Good Condition	•
Interior Radiator	Good Condition	•

Fueling System		
Intake Manifold	Good Condition	•
Throttle	Good Condition	-
Turbo	Within Specification	-
Injectors	Good Condition	•
Fuel Pump	Good Condition	•
Fuel Lines	Good Condition	•

Ignition System		
Ignition Coils	Good Condition	-
Glow Plugs	Not Applicable	•
Distrubutor	Not Applicable	-
HT Leads	Not Applicable	-



# **BOSCH INSPECTION REPORT**

Steering & Suspension		
Steering Rack	Within Specification	•
Power Steering Pump	Good Condition	•
Wheel Alignment	Not Applicable	•
CV Joints	Good Condition	•
CV Boots	Good Condition	•
Shocks Front	Good Condition	•
Shock Mountings Front	Renewed	•
Shocks Rear	Within Specification	•
Stabilizer Links	Renewed	•
Wheel Bearings	Within Specification	•
Bearing Hubs	Good Condition	•
Control Arms	Renewed	•
Sideshafts/Seal	Within Specification	•
Propshaft	Within Specification	•
Wheel Nuts/Studs	Good Condition	•
Tyres & Spare	Within Specification	•
Mag Wheels/Hub Caps	Within Specification	•

Transmission & Clutch		
Clutch Kit	Not Applicable	•
Clutch Master	Not Applicable	•
Clutch Slave	Not Applicable	<b>•</b>
Clutch Cable	Not Applicable	•
Gearbox	Within Specification	•
Gear & Diff oil	Within Specification	•
Auto Transmission	Good Condition	•
Gear Selector	Good Condition	•
Gear Linkages	Good Condition	•

Ignition System		
Diagnostics	Within Specification	-
Cyl Leakage Test	Within Specification	-
Road Test	Within Specification	-
Handling	Good Condition	•

#### **Concluding Remarks**

### Bosch Technician

**NEW Technician** 

-Select-

### General Comments

Date of Inspection



## BOSCH CAR SERVICE PRETORIA

a: 564 Steve Biko Road, Gezina, Pretoria 0084 t: 012 335 5737 e: reception@boschgezina.co.za

