

All System Diagnostic Report

The Report is created by **THINKCAR**

Repair Shop

Shop Name:bosch service centre

Address:564 Steve Biko Road

Telephone:0123355737

Email:juan-dre@boschgezina.co

Sn:988579800333

Time:2024-07-12 11:34:44

Technician Name:bote

Order no:

Service fee:

Notes:

Vehicle Information

Year:2016.09

Make:BMW

Model:320i

VIN:WBA8A16080NU39542

Displacement:G 1.6 MPI

Odometer:127433 miles

Vehicle Software Version:V10.30

Inspection Result

The following systems are OK:

- 1.SRS (Supplemental Inflatable Restraint System - AIRBAG/SGM-SIM)
- 2.ZGM (Central Gateway Module)
- 3.ECM (Engine Control Module - DME/DDE)
- 4.TCM (Transmission Control Module - EGS)
- 5.ICM (Integrated Chassis Management)/RLM_2L (Tail Light Module, Inner Left)
- 6.ABS (Anti-Lock Braking System - DSC)
- 7.EPS (Electronic Power Steering)
- 8.CAS (Car Access System - CAS/FEM/BDC)
- 9.FZD (Function Center, Roof)
- 10.GWS (Gear Selector Switch)
- 11.IC (Instrument Cluster - INSTR)
- 12.ECALL (Emergency Call)
- 13.CIC (Car Information Computer)
- 14.ZBE/CON (Controller)
- 15.FRM (Footwell Module)/TSGFA (Driver Door Control Unit)
- 16.AC (Air Conditioning - IHKA)